

# **HydraWrap**<sup>®</sup> (Fiber Reinforced Polymer)

### Market

Power Generation

## Challenge

The challenge was to repair condenser water boxes.

## **Engineered Solution**

The solution utilized the HydraWrap Structural Composite Repair System.

## Scope

A customer requested repair and coating to four water boxes, each box measuring approximately 290 square feet. Engineers walked down the project, reviewed drawings, accessed system operating parameters and provided an engineered solution.

#### Solution

Each water box was grit blasted to SSPC-6 to obtain a near white surface profile. Two layers of bidirectional carbon fiber were installed on the interior surfaces of each water box while ensuring a smooth transition to all inlet and outlet connections. The HydraWrap encapsulated all pinhole leaks and provided structural integrity to the wall area of the system.







