



Market

Drinking Water

Challenge

The client had discovered that their new piping was leaking at the joints. Three leaks were found to be the culprit.

Engineered Solution

HydraTech provided three HydraTite Internal Pipe Joint Seals manufactured with a 54" diameter.

Scope

One of the three sections of pipe made a 20-foot drop and was only accessible by narrow stairs. First, the surface of the pipe near the joints was prepped to ensure a smooth surface for installation. The rubber was then put in position and the stainless steel bands were expanded to lock the rubber in place.



Solution

HydraTite provided a solution quickly and was a more cost-effective solution compared to replacement. The system's joints were reinforced and service life was prolonged.

HydraTech Engineered Products, LLC

HydraTech Field Services, LLC

10448 Chester Road, Cincinnati, Ohio 45215 Phone: (513) 827-9169 Fax: (513) 827-9171

<https://hydratechllc.com>

<https://hydratechllc.com/services/field-services/>