



Market

Civil / Infrastructure

Challenge

An inspection of the Markland bridge revealed deteriorated concrete, exposed rebar, and areas needing repair. Traffic crossing the bridge complicated repairing the spalling concrete. A solution was required that provided a long-term repair while maintaining traffic flow patterns.

Engineered Solution

Concrete mortar mix and fiberglass-reinforced plastic (FRP) were chosen to repair and reinforce the aging concrete.

Scope

HydraTech set up traffic control so that the snoopers truck could be positioned on the bridge and lower the crew to the damaged portions of the bridge. Loose concrete was removed and the surface was pressure washed. The concrete mortar was applied to restore the profile of the bridge's damaged surfaces. Next epoxy was applied to the newly created profile. The FRP wrap was then applied. 626 sq ft of FRP was applied to multiple repair locations. The entire project was completed in approximately 2 weeks.

Solution

HydraTech was able to repair and protect the damaged portions of the bridge. FRP repairs provide a time-efficient and cost-effective option to conventional bridge restoration methods.



HydraTech Engineered Products, LLC
HydraTech Field Services, LLC
10448 Chester Road, Cincinnati, Ohio 45215
Phone: (513) 827-9169 Fax: (513) 827-9171
<https://hydrattechllc.com/services/field-services/>

