



INTERNAL PIPE

HydraTite®

JOINT SEAL

Market

Municipal Drinking Water

Challenge

Water Treatment Facility Leak.

Engineered Solution


HydraTite Joint Seal with EPDM 60" and 54".

Scope

Crews installed a joint seal around a 60" coupling that had leaked and a 54" vertical tee. A kit with shims and an expander was needed.

Solution

The pipe was sealed.



HydraTech Engineered Products, LLC
HydraTech Field Services, LLC
10448 Chester Road, Cincinnati, Ohio 45215
Phone: (513) 827-9169 Fax: (513) 827-9171
<http://www.hydratechllc.com>

