



INTERNAL PIPE

HydraTite®

JOINT SEAL

Market

DOT

Challenge

There were multiple sections of precast concrete culverts within ODOT District 7 that were showing signs of severe separation. The joint separation needed to be stopped so that the above roadways did not become damaged from infiltration/soil erosion.

Engineered Solution

The proposed solution utilized the HydraTite Internal Pipe Joint Seal.

Scope

The culvert joints needing repair were at the following locations: US 36 in Darke County, SR 287 in Logan County, SR 292 in Logan County, and two sections of interstate 71 in Shelby County. Extra-wide HydraTite seals were installed at these locations in the following sizes: six 60" diameter round, one 66" diameter round, eleven 48" by 76" elliptical, and two 43" by 68" elliptical.

Solution

Each pipe joint of concern was cleaned, smoothed with cement, and sealed with a HydraTite Internal Pipe Joint Seal. The installed HydraTite seals now prevent further separation of the existing pipe joints. This will help ensure infiltration does not cause soil loss under the existing roadways. The project was completed with minimal traffic disruption and at a fraction of the cost of other methods. This lifetime repair was successfully executed by HydraTech at 30 % below the engineer's estimate.



HydraTech Engineered Products, LLC
HydraTech Field Services, LLC
10448 Chester Road, Cincinnati, Ohio 45215
Phone: (513) 827-9169 Fax: (513) 827-9171
<http://www.hydratechllc.com>

