



INTERNAL PIPE HydraTite® JOINT SEAL

Market

Drinking & Irrigation

Challenge

Following a major earthquake in Chile in 2010, a drinking water and irrigation system experienced structural displacement within a pipe bridge system. The seismic event caused beam movement and separation at multiple bridge joints, creating visible gaps where the exterior of the bridge could be seen from inside the structure.

The bridge consisted of dual arched aqueducts measuring 83 cm by 151 cm with a flat invert. This unique shape, combined with joint separation caused by seismic movement, allowed persistent leakage at multiple locations in this concrete structure.

Although external seals had previously been installed, they did not fully eliminate leakage under operating conditions. With a maximum operating pressure of 10 meters of water column and maximum flow velocities of 3.6 m/s, infiltration posed an ongoing risk to the plant's reliability. Multiple joints were identified as critical points of concern, requiring a custom, internally installed sealing solution.

Engineered Solution

HydraTech engineered and manufactured custom HydraTite® Internal Pipe Joint Seals specifically adapted for the arched aqueduct geometry and flat invert, demonstrating the system's flexibility beyond standard round pipe applications. The seals were equipped with two 6-piece stainless steel retaining bands.



The initial repair plan utilized extra-wide (EW) rubber seals, mechanically locked into place using stainless steel retaining bands, anchors, and hold-downs to ensure stability under flow and pressure conditions. The seals were designed to conform to the non-cylindrical shape while maintaining full circumferential contact across the joints.

Scope

The customized HydraTite® sealing system successfully eliminated leakage at all repaired joints despite their non-standard geometry. By adapting seal design to an arched aqueduct with a flat invert and rapidly supplying a wider solution when conditions demanded it, HydraTech restored watertight integrity where external sealing methods had failed.

This project demonstrated HydraTite®'s ability to deliver flexible, field-responsive, trenchless sealing solutions for critical infrastructure, even in irregular shapes, followed by installation of a custom 59.5-inch extra-wide HydraTite® seal secured with two 2-piece stainless steel retaining bands. All work was completed over two days, working onsite, with all joints successfully sealed.

Solution

All repaired joints were successfully sealed, eliminating infiltration. The HydraTite® system restored watertight integrity across both corrugated-to-concrete transitions and the additional compromised joint, without excavation or traffic disruption. This project demonstrated HydraTite®'s ability to adapt to complex transition geometries, manage dimensional variability, and deliver long-term performance using custom-engineered trenchless solutions.



HydraTech Engineered Products, LLC
HydraTech Field Services, LLC
10448 Chester Road, Cincinnati, Ohio 45215
Phone: (513) 827-9169 Fax: (513) 827-9171
<http://www.hydratechllc.com>

